

MOTM-800 ADSR Envelope Generator Assembly Instructions & Owner's Manual

Synthesis Technology 6625 Quail Ridge Dr. Fort Worth, TX 76180 (817) 498-3782 www.synthtech.com

MOTM-800 PARTS LIST

Please carefully check that all parts are in your kit. If you have a suspected shortage, please call or email. If you get free extra stuff, keep it for next time.

Capacitor bag, containing the following 9 parts:	
2ea 10mfd, 25V or 50V Electrolytic 1ea 3M3mfd, bi-polar Electrolytic 1ea 1000pf (marked 1N or 102) yellow box 1ea 0.01mfd (marked 10N or 103) yellow box 4ea 0.1mfd (marked 104) ceramic axial	C1, C2 C9 C3 C4 C5, C6, C7, C8
esistor bag, containing the following 16 parts:	
4ea 100K 5% (brown, black, yellow) 3ea 10K 5% (brown, black, orange) 3ea 47K 5% (yellow, violet, orange) 2ea 2K 5% (red, black, red) 2ea 1K 5% (brown, black, red) 1ea 5K1 5% (green, brown, red) 1ea 1M 5% (brown, black, green)	R10, R11 R1, R2, R15 R3, R4, R8 R13, R14 R12, R16 R9 R7
IC bag, containing the following 9 parts:	
1ea TL072 op amp 1ea TLC555CP CMOS timer 1ea HCF4066BE Quad CMOS switch 2ea 2N3904 NPN transistor 4ea 1N4148 signal diode	U3 U2 U1 Q1, Q2 D1, D2, D3, D4
Misc #1 bag, containing the following 3 parts:	
2ea Axial ferrite beads (plain, gray things)L1, L2 1ea MTA-156 power connector	JP1
Knobs, 4ea, ALCO PKES90B1/4	
Jacks, 4ea Switchcraft 112A Pots, containing the following:	
3ea 1M log, Bourns 91A1DB28D25 1ea 10K linear, Bourns 91A1AB28B15	VR1, VR2, VR4 VR3
Front panel	

MOTM-800 PARTS LIST (cont) Mounting bracket, small Wire bag, containing the following 6 wires: 3ea RG-174 coax, 4 1/2 inches 1ea 3-wire set 22ga, 2 1/2 inches (white/orange/gray) 1ea 22ga wire 2 ½" 1ea Power Cable, 20" Hardware bag, containing: 4ea #8-32 x 3/8 black screws (for mounting module to rack) 4ea #6-32 x 3/8 zinc screws (for attaching pc board to bracket) 4ea 1/8 inch aluminum spacers 6ea #6 KEPS nuts (2 for attaching bracket to front panel, 4 for pc board) 4ea small tie-wraps Organic Solder No-clean Solder

PC Board, MOTM-800